

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

B.P.O. Elks Lodge # 15 (Convention
Center Site, District of Columbia)
919 H Street, NW
Washington, D.C.

HABS No. DC-386

Documentation: 6 exterior photos (1979)
6 historic interior photos
17 data pages (1980)
1 set field records (1979)

William Edmund Barrett, Photographer 1979

DC-386-1 SOUTH (FRONT) ELEVATION
DC-386-2 GENERAL VIEW FROM EAST
DC-386-3 SOUTH AND EAST ELEVATIONS
DC-386-4 SOUTH AND WEST ELEVATIONS
DC-386-5 DETAIL, EXTERIOR LAMP POST
DC-386-6 DETAIL, SECOND FLOOR SHOWING BUSTS

HISTORIC VIEWS, ELKS LODGE COLLECTION, DATE AND PHOTOGRAPHER UNKNOWN

DC-386-7 INTERIOR, BALLROOM
DC-386-8 INTERIOR, TREASURER'S OFFICE
DC-386-9 INTERIOR, LOBBY
DC-386-10 INTERIOR, OFFICE
DC-386-11 INTERIOR, LODGE ROOM
DC-386-12 INTERIOR, ELEVATOR